

Crane Tool Box Talk



All competent crane operators must have successfully completed a training program that includes all of the elements set out in the Bermuda *Occupational Safety and Health Regulations, 2008*.

Operators must ensure all safety system indicators are functioning properly and enabled at all times.

Inspection and log books must be completed daily.

Equipment must not be overloaded.

Avoid lifting loads above workers or the public.

It is very important workers pay attention around crane operations, obey all warning signs and stay out of way of moving parts.

Before work is performed in the area, a site evaluation should be completed to identify and correct any hazards present.

Power lines must be located and barricades or signs should be posted to ensure minimum distance is maintained.

Report any unsafe acts, malfunctions or problems to your supervisor.

Inspections must be completed and any defects properly repaired before the equipment is used.

Structural components of the equipment must be working properly.

Both the employer or contractor, and the supplier have a responsibility to ensure that every hoist, crane and lifting device, including all rigging, used or supplied for use at a place of employment is designed, constructed, installed, maintained and operated to perform safely any task for which the equipment is used.